10/619918





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Ventor(s): Warren M. Farnworth

Patent No.: 6,890,801 B2

Issued: May 10, 2005

For: STEREOLITHOGRAPHIC
METHODS FOR FABRICATING
HERMETIC SEMICONDUCTOR DEVICE
PACKAGES AND SEMICONDUCTOR
DEVICES INCLUDING
STEREOLITHOGRAPHICALLY
FABRICATED HERMETIC PACKAGES

Attorney Docket No.: 2269-4212.6US

CERTIFICATE OF MAILING

I hereby certify that this correspondence along with any attachments referred to or identified as being attached or enclosed is being deposited with the United States Postal Service as First Class Mail on the date of deposit shown below with sufficient postage and in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

January 26, 2006

Date

Signature

Erika Gandre Name (Type/Print)

ane (Typer Int)

Certificate

FEB 0.2 2006

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANT'S MISTAKES (37 C.F.R. § 1.323) AND PATENT OFFICE MISTAKES (37 C.F.R. § 1.322)

Attn.: Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

It is noted that a combination of Applicant and Patent Office errors appear in this patent of a typographical nature or character and correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. A certificate of correction in the form attached hereto is requested.

02/01/2006 HGUTEMA1 00000010 6890801

01 FC:1811

100.00 OP

Please send the Certificate to:

Name:

Brick G. Power

Address:

TraskBritt

P.O. Box 2550

Salt Lake City, Utah 84110

The fee of \$100.00 as required by 37 C.F.R. § 1.20(a) is enclosed.

Attached hereto in duplicate is Form PTO/SB/44 with at least one copy being suitable for printing.

Respectfully submitted,

Brick G. Power

Registration No. 38,581 Attorney for Applicant(s)

TRASKBRITT P.O. Box 2550

Salt Lake City, Utah 84110-2550

Telephone: 801-532-1922

Date: January 26, 2006

BGP/csw

Enclosures: PTO/SB/44 in duplicate

Check No. 22398 in the amount of \$100.00

Document in ProLaw

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,890,801 B2

Page 1 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page:

In the section (56) References Cited U.S. PATENT DOCUMENTS

page 2, column 1, 7th entry:

change "4,987,260 A 1/1991 Butt" to --4,967,260 A

10/1990 Butt--

page 2, column 1, 34th entry:

change "5,430,668" to --5,430,666--

In the drawings:

In Fig. 15,

please relocate reference numeral --100-- and redirect the lead line extending therefrom to rest upon the top surface of platform 90

In the specification:

COLUMN 2, LINES 37, 45, 47, 49,

change "'100" to --'100--

COLUMN 2, LINE 48, COLUMN 7, LINE 2,

change "maybe" to --may be-change "FIG. 1," to --FIG. 11,--

COLUMN 7, LINE 55, COLUMN 9, LINE 12,

change "is therefore" to --is, therefore,--change "layers," to --layers--

COLUMN 10, LINE 7, COLUMN 12, LINE 62.

change "die 12" to --dice 12-change "inches)" to --inch)--

COLUMN 13, LINE 41,

change "if level 88" to --if surface level 88--

COLUMN 13, LINE 65, COLUMN 14, LINE 11,

change "inches)" to --inch)-change "108A" to --108--

COLUMN 14, LINE 25,

change "first particle layer 108" to --first particle

layer 108a--

MAILING ADDRESS OF SENDER:

PATENT NO. 6,890,801 B2

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,890,801 B2

Page 2 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the specification (continued):

COLUMN 15, LINE 34,

change "SINTERSTATION®2000" to

--SINTERSTATION® 2000--

COLUMN 17, LINE 33,

change "direct beam 98," to --direct laser beam 98,--

COLUMN 17, LINE 41,

change "108a to each" to --108b to each--

COLUMN 17, LINE 43,

change "have been" to --has been--

COLUMN 17, LINE 47,

change "back side 13)." to --backside 13).--

COLUMN 19, LINE 21,

change "Accordingly," to -- Accordingly,--

In the claims:

CLAIM 18, COLUMN 20, LINE 53,

change "saidthe" to --the--

MAILING ADDRESS OF SENDER:

PATENT NO. 6,890,801 B2

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies



Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,890,801 B2

Page 3 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please replace FIG. 15 with the following corrected figure:




Fig. 15

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,890,801 B2</u>

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,890,801 B2

Page 1 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page:

In the section (56) References Cited **U.S. PATENT DOCUMENTS**

page 2, column 1, 7th entry:

change "4,987,260 A 1/1991 Butt" to --4,967,260 A

10/1990 Butt--

page 2, column 1, 34th entry:

change "5,430,668" to --5,430,666--

In the drawings:

In Fig. 15,

please relocate reference numeral -- 100-- and redirect the lead line extending therefrom to rest upon the top surface of platform 90

In the specification:

COLUMN 2. LINES 37,

45, 47, 49, change "'100" to --'100--

COLUMN 2. LINE 48, change "maybe" to --may be--COLUMN 7, LINE 2,

change "FIG. 1," to --FIG. 11,--

COLUMN 7. LINE 55.

change "is therefore" to --is, therefore,--

COLUMN 9, LINE 12, COLUMN 10, LINE 7,

change "layers," to --layers-change "die 12" to --dice 12--

COLUMN 12, LINE 62, COLUMN 13, LINE 41, change "inches)" to --inch)-change "if level 88" to --if surface level 88--

COLUMN 13, LINE 65,

change "inches)" to --inch)--

COLUMN 14, LINE 11.

change "108A" to --108--

COLUMN 14, LINE 25,

change "first particle layer 108" to --first particle

layer 108a--

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,890,801 B2</u>

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6.890.801 B2

Page 2 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the specification (continued):

COLUMN 15, LINE 34,

change "SINTERSTATION®2000" to

--SINTERSTATION® 2000--

COLUMN 17, LINE 33,

change "direct beam 98," to --direct laser beam 98,--

COLUMN 17, LINE 41,

change "108a to each" to --108b to each--

COLUMN 17, LINE 43,

change "have been" to --has been--

COLUMN 17, LINE 47,

change "back side 13)." to --backside 13).--

COLUMN 19, LINE 21,

change "Accordingly," to -- Accordingly, --

In the claims:

CLAIM 18, COLUMN 20, LINE 53,

change "saidthe" to --the--

MAILING ADDRESS OF SENDER:

PATENT NO. 6,890,801 B2

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies



. . .

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,890,801 B2

Page 3 of 3

DATED

May 10, 2005

INVENTOR(S):

Warren M. Farnworth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please replace FIG. 15 with the following corrected figure:




Fig. 15

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,890,801 B2</u>

Brick G. Power 230 South 500 East, Suite 300 Salt Lake City, Utah 84102 USA

No. of additional copies